


Principles of Re-establishment Exercise 5

Original Survey Marks Missing but Occupation Existing



In 1951, the results of a Crown survey to define the boundary between Crown allotments 1 and 2 are shown on the first diagram above. A recently constructed fence is shown not to be coincident with the adopted boundary.

In a recent survey of the boundary it was found that the pegs placed in 1951 have been destroyed but the fence, which is more than 50-years-old, still exists.

Question:

Where does the Crown boundary lie?

Answer:

In this case, the relationship between the adopted boundary and occupation remains as it was in the 1951 survey. The fence is not the Crown boundary.



© The State of Victoria, Department of Sustainability and Environment, 2009

Disclaimer: This publication may be of assistance to you but the State of Victoria and its employees do not guarantee that the publication is

without flaw of any kind or is wholly appropriate for your particular purpose and therefore disclaims liability for any error, loss or other consequence which may arise from you relying on any information in this publication.